

**PRELIMINARY SUMMARY OF MAP ACTIONS**Community: Kalispell, MontanaCommunity No.: 300025

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previous Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

**1. LOMRs and LOMAs Incorporated**

The modifications effected by the LOMRs and LOMAs listed below have been reflected on the Preliminary copies of the revised FIRM panels. However, these LOMRs and LOMAs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR	02-08-0300P	7/2/2003	Kalispell Hampton Inn Floodplain Development	3000250005C	30029C1805G

**2. LOMRs and LOMAs Not Incorporated**

The modifications effected by the LOMRs and LOMAs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMR or LOMA issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMRs and LOMAs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single letter that reaffirms the validity of the previous LOMC.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR-F	94-08-187A	10/13/1994	Woodland Park Addition, Lot 14, Block 3—650 Sylvan Court	3000250005C	30029C1810G
LOMA	97-08-087A	3/25/1997	Belmar Addition, Lots 13-14—1859 & 1863 North Belmar Drive	3000250005C	30029C1815G
LOMR-F	97-08-342A	11/6/1997	Belmar Addition, Lots 13-14—1859 & 1863 North Belmar Drive	3000250005C	30029C1815G
LOMA	00-08-143A	6/14/2000	Park Addition, Lot 2— 1260 West Idaho	3000250005C	30029C1805G
LOMR-F	02-08-386A	10/15/2002	Meridian Complex East, Lot 1 & Meridian Complex, Lot 2—157 North Meridian Road	3000250005C	30029C1805G

### 3. LOMRs and LOMAs Superseded

The modifications effected by the LOMRs and LOMAs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMRs and LOMAs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will Be Superseded
None				

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

### 4. LOMRs and LOMAs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. We will review the data previously submitted for the LOMR or LOMA requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
None					